
Regulatory Instructions for Use

Avaya IP Office - Small Office Edition Operation in the US

The antenna must be mounted 2 meters away from the user.

Any changes or modifications not expressly approved by Avaya ECS Ltd could void the user's authority to operate the equipment.

Avaya IP Office - Small Office Edition Operation in Australia

Connection

Connection of IP Office - Small Office Edition products must be via a Line Isolation Unit with a telecommunications compliance label.

BRI Interface

During the configuration, ensure "000" emergency number is not barred, by performing the following:

Short Code: "000"

Telephone No.: "000;"

Function: "Dial Emergency"

Connections to TS013, the following Bearer Capabilities shall not be used:

7kHz Audio

Video

Restricted Digital Information

If unknown type of number is used in calling party number, the network will use the default CLI.

The system must be configured for Point to Multi point connection to comply with Austel requirements for connecting to TS013 circuits.

Avaya IP Office - Small Office Edition Operation in Canada

Industry Canada Notification (DoC)

This equipment meets the applicable Industry Canada Terminal Equipment Technical Specifications. This is confirmed by the registration number. The abbreviation, IC, before the registration number signifies that registration was performed based on a Declaration of Conformity indicating that Industry Canada technical specifications were met.

It does not imply that Industry Canada approved the equipment.

"NOTICE: The Ringer Equivalence Number (REN) for this terminal equipment is 1. The REN assigned to each terminal equipment provides an indication of the maximum number of terminals allowed to be connected to a telephone interface. The termination on an interface may consist of any combination of devices subject only to the requirement that the sum of the Ringer Equivalence Numbers of all the devices does not exceed five."