FCC TEST REPORT Report No. : F382701

1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW


SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

Page No. : 1 of 3 Issued : Sep, 16, 2003

: RGWGWM2UBA

FCC ID

FCC TEST REPORT Report No. : F382701



SIDE VIEW

FCC ID : RGWGWM2UBA SPORTON International Inc.

TEL: 886-2-2696-2468

Page No. : 2 of 3 Issued : Sep, 16, 2003 FAX: 886-2-2696-2255

FCC TEST REPORT Report No. : F382701

1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID : RGWGWM2UBA

Page No.: 3 of 3

Issued : Sep, 16, 2003