



Elliott Laboratories Inc.
www.elliottlabs.com

684 West Maude Avenue
Sunnyvale, CA 94085-3518

408-245-7800 Phone
408-245-3499 Fax

October 22, 2003

American TCB
6731 Whittier Ave
Suite C110
McLean, VA. 22101

RE: Lasershield FCC ID RIHK0011500

Tim,

Below are my answers for each issue in Blue:

1) Please provide pages 5 & 6 of the R53085-cover letters as a separate exhibit to be uploaded to the FCC site.

Corrected and uploaded as separate letters.

2) The FCC ID and Identifier must be located on a single line as given in 2.925(a)(1). The FCC ID shown in the label and test report (1 & 4 of 15, 2 of 7), does not match the application 731 form (RIHK0011500 vs. RIHK001150). Please confirm the correct FCC ID and update the label and/or affected exhibits as necessary. Additionally, the drawing showing placement of the label does not look like the device in this application. Please provide an updated photograph or drawing showing the placement of the label.

Corrected. FCC ID is RIHK0011500. Uploaded revised label and report.

3) Page 4 of 15 states that the device does have predetermined transmissions, which are not allowed. Please explain.

This statement was a typo on our behalf. There are NO predetermined transmissions.
Corrected in report and uploaded.

Sincerely,

Jennifer Sanchez