



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

March 23, 2004

RE: Electronics Line 3000 Ltd.

FCC ID: RIYEL2600-PI

I have a few comments on the above referenced Application.

EMC Report

- 1) We have not received the plots referenced to show/support compliance to 15.231(a)(2). This information should support the information in #2 below. Please provide.
- 2) There is contradictory information within the application that needs to be corrected:
  - a) The test report (Section 3.1.1) describes 3 x 800 ms bursts with 1 second between, while the new operational description provided mentions 2 x 500 ms burst. Please confirm which is correct, and provide either a corrected operational description or test report as necessary.
  - b) The test report (Section 3.1.1) states that there are not supervisory transmissions, while information just provided from the applicant states there is. Please confirm which is correct, and provide either a corrected operational description statement or test report as necessary

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.