



HERMON LABORATORIES

February 4, 2008

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated January 7, 2008; Electronics Line 3000 Ltd.
FCC ID:RIYEL2606, ATCB005790

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The corrected file "Label_location_18074_rev1" was uploaded on February 4, 2008.
- 2) The applicant confirms that the file "Schematic_diagram_18074" does include RF part (utilizes U2 of AT1466 type as shown in "Operational_description_18074").
- 3) The adjusted file "User_manual_18074_rev1" was uploaded on February 4, 2008.
- 4) The adjusted test report "ELERAD_FCC.18074_rev1" with corrected Table 7.2.3 was uploaded on February 4, 2008.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories