FCC TEST REPORT Report No.: F392607

## 1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 



**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : RK9-WM1170

Page No. : 1 of 3

Issued : Oct. 31, 2003

FCC TEST REPORT Report No.: F392607



SIDE VIEW

FCC ID : RK9-WM1170 SPORTON International Inc. TEL: 886-2-2696-2468

Page No. : 2 of 3 Issued : Oct. 31, 2003 FAX: 886-2-2696-2255


FCC TEST REPORT Report No.: F392607

## 1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc. TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID : RK9-WM1170

Page No. : 3 of 3

Issued : Oct. 31, 2003