



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 4, 2005

RE: Tech Dynamic Limited

FCC ID: RKIC51-A05035-XX

ATCB#: ATCB002829

I have a few comments on this Application.

1. The label must have a colon at the end of FCC ID: and then the number. You have left the colon out on the label sample. Please revise label. The label should read:

FCC ID: RKIC51-A05035-XX

2. In the test report on page 30 the data for 300.63 MHz vertical position is failing by 13.72 dB. Please retest the EUT for spurious emission and explain how failure was corrected.

Thank you,

Douglas E. Noble
Examining Engineer

[mailto: dnoble@americanTCB.com](mailto:dnoble@americanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.