

US Tech
Test Report:
Date:
Model(s):
FCC ID:
IC:
Customer:

FCC Part 15.249/ RSS 210
13-0180
September 18, 2013
SW-2XAA
RMS0217642XAA
10872A-SW2XAA
Swirl Networks

EXTERNAL PHOTOGRAPHS




Figure 1. Top View

US Tech
Test Report:
Date:
Model(s):
FCC ID:
IC:
Customer:

FCC Part 15.249/ RSS 210
13-0180
September 18, 2013
SW-2XAA
RMS0217642XAA
10872A-SW2XAA
Swirl Networks




Figure 2. Bottom View

US Tech
Test Report:
Date:
Model(s):
FCC ID:
IC:
Customer:

FCC Part 15.249/ RSS 210
13-0180
September 18, 2013
SW-2XAA
RMS0217642XAA
10872A-SW2XAA
Swirl Networks




Figure 3. Side 1

US Tech
Test Report:
Date:
Model(s):
FCC ID:
IC:
Customer:

FCC Part 15.249/ RSS 210
13-0180
September 18, 2013
SW-2XAA
RMS0217642XAA
10872A-SW2XAA
Swirl Networks




Figure 4. Side 2

US Tech
Test Report:
Date:
Model(s):
FCC ID:
IC:
Customer:

FCC Part 15.249/ RSS 210
13-0180
September 18, 2013
SW-2XAA
RMS0217642XAA
10872A-SW2XAA
Swirl Networks




Figure 5. Side 3

US Tech
Test Report:
Date:
Model(s):
FCC ID:
IC:
Customer:

FCC Part 15.249/ RSS 210
13-0180
September 18, 2013
SW-2XAA
RMS0217642XAA
10872A-SW2XAA
Swirl Networks



Figure 6. Side 4