

SUBJECT: 802.11a disabled

FCC ID: ROSTEMPUS-1

2 March 2010

To Whom It May Concern:

Please be advised that the 802.11a functionality has been disabled in the Tempus IC. This has been achieved within the module's driver software.

Respectfully



Chris Hannan

Regulatory Affairs and Operations Manager

Registered Office:

Remote Diagnostic Technologies Ltd

The Old Coach House, The Avenue, Farleigh Wallop, Hampshire, RG25 2HT, UK

Registered in England No 3321782 VAT No 692 9012 19 LLC No 4148022

T +44 (0) 1256 362 400

F +44 (0) 1256 362 415

www.rdtltd.com

info@rdtltd.com