

11 December 2007

American TCB
6731 Whittier Avenue
McLean VA 22101

RE: Larco
Response to 29 November 2007 Comments

FCC ID: RQL336806

In response to your comments on the above submittal from 29 November 2007.

1. ATCB Comments: The internal photos need to show the board with the sensor removed and also the back side of the board. Please revise internal photos.

RESPONSE: Revised exhibit uploaded.

2. ATCB Comments: For Industry Canada the label needs to show the model number. Please revise label.

RESPONSE: Revised exhibit uploaded.

3. ATCB Comments: The Schematics are almost unreadable. Please upload a clearer schematic exhibit.

RESPONSE: Revised exhibit uploaded. This exhibit is coming from the manufacturer, I hope this one is better but let me know if not and I will request again.

4. ATCB Comments: The limit for the fundamental in 15.245 is 128 dBuV @ 3 meters. The limit that was used is 135.5 dBuV @ 3 meters. Please explain.

RESPONSE: Revised radiated emissions Run 1 datasheet and uploaded revised test report.

Please let us know if anything further is required.

Susan L Rupp

Susan L Rupp, Technical Writer
TÜV America Inc
Tel: 651 638 4585 / Fax: 651 638 0298
srupp@tuvam.com