

Hyundai Corporation

Address: 140-2, Kye-dong, Chongro-ku, Seoul, South Korea.  
Tel: 82-2-746-1395 Fax: 82-2-746-1051

Attestation Letter

2015-06-05


To:  
Bay Area Compliance Laboratories Corp.  
1274 Anvilwood Avenue  
Sunnyvale, CA 94089

Dear Sir or Madam:

The RF chip, model: MT6276A which installed in FCC ID: RQQHLT-W215 supports GSM, GPRS functions. For use in the US this chip will not support/enable the HSDPA and HSUPA function. The HSDPA and HSUPA function has been shielded by the manufacturer using the software.

Best Regards,

Sincerely,

Signature: 

Kyunghee Kim

Sales assistant