




INTERTEK TESTING SERVICES

Report No.: HK09010545-1  
 Model No.: 09995(TX)  
 Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 0 dBm      Att 30 dB      RBW 3 MHz      Delta 1 [T1 ]  
 \*VBW 3 MHz      -0.07 dB  
 SWT 20 ms      15.980000 ms



Tested By: Michael Lenny  
 (Michael Lenny)

Date: 2011/09

Checked By: Bob (Cowan)

Date: 2011/09

Test Result: Pass / Fail /  NA

INTERTEK TESTING SERVICES


Report No.: HK09010545-1  
 Model No.: 09995(TX)  
 Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 0 dBm Att 30 dB RBW 3 MHz Delta 1 [T1]  
 \*VBW 3 MHz -1.01 dB  
 SWT 20 ms 1.340000 ms

1 AP  
 CLRWR



Tested By: Michael Leung  
 (Michael Leung)

Date: 20/1/09

Checked By: Paul (Glen)

Date: 20/1/09

Test Result: Pass / Fail / NA


INTERTEK TESTING SERVICES

Report No.: HK09010545-1  
 Model No.: 09995(TX)  
 Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 0 dBm      Att 30 dB      RBW 3 MHz      Delta 1 [T1 ]  
 \*VBW 3 MHz      -0.84 dB  
 SWT 20 ms      500.000000 μs



Tested By: Michael Leung  
 (Michael Leung)

Date: 20/1/09

Checked By: [Signature]  
 (Eric Chen)

Date: 20/1/09

Test Result: Pass / Fail / NA