

INTERTEK TESTING SERVICES

hp

Report No.: 040187
Model No.: 60348


Pursuant to FCC Part 15 Section 15. 225 b Emissions Requirement

MKR 4.34 KHZ
-26.73 dB

REF 10.0 dBm

AT 20 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: (Signature)
Date: 2-6-04
Checked By: (Signature)
(Anthony Chen)
Date: 9/6/04
Test Result: Pass / Fail / NA

START 13.55300 MHz

STOP 13.56700 MHz

#RES BW 1.0 KHZ

VBW 1 KHZ

#SWP 30.0 sec

INTERTEK TESTING SERVICES

Report No.: 0410187
Model No.: 60348

hp

Pursuant to FCC Part 15 Section 15. 225 c Emissions Requirement MKR 147.8 KHZ


REF 10.0 dBm

AT 20 dB

-55.69 dB

PEAK
LOG
10
dB/

VA SB
SC FC
CORR



Tested By:

(Signature)

Date: 2-6-04

Checked By:

(Signature)
Anthony Chan

Date: 9/6/04

Test Result: Pass / Fail / NA

START 13.4100 MHz

STOP 13.7100 MHz

#RES BW 1.0 KHZ

VBW 1 KHZ

#SWP 30.0 sec

INTERTEK TESTING SERVICES

Report No.: 0410187
Model No.: 60348

hp


Pursuant to FCC Part 15 Section 15. 225d Emissions Requirement MKR 450.0 KHZ

REF 10.0 dBm

AT 20 dB

-72.87 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: [Signature]
(Chapman)

Date: 2-6-04

Checked By: [Signature]
(Anthony Chan)

Date: 9/6/04

Test Result: Pass / Fail / NA

START 13.1100 MHz

STOP 14.0100 MHz

#RES BW 1.0 KHZ

VBW 1 KHZ

#SWP 30.0 sec