Appendix B. Test Photos

 SPORTON International Inc.
 Page No.
 : B1 of B6

 TEL: 886-3-327-3456
 Issued Date
 : Oct. 22, 2010

 FAX: 886-3-318-0055
 FCC ID
 : RSE-TG703

1. Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 Page No.
 : B2 of B6

 TEL: 886-3-327-3456
 Issued Date
 : Oct. 22, 2010

 FAX: 886-3-318-0055
 FCC ID
 : RSE-TG703



SIDE VIEW


 SPORTON International Inc.
 Page No.
 : B3 of B6

 TEL: 886-3-327-3456
 Issued Date
 : Oct. 22, 2010

 FAX: 886-3-318-0055
 FCC ID
 : RSE-TG703

1.1. Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 Page No.
 : B4 of B6


 TEL: 886-3-327-3456
 Issued Date
 : Oct. 22, 2010

 FAX: 886-3-318-0055
 FCC ID
 : RSE-TG703

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON International Inc.TEL: 886-3-327-3456
FAX: 886-3-318-0055

 Page No.
 : B5 of B6


 Issued Date
 : Oct. 22, 2010

 FCC ID
 : RSE-TG703

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 Page No.
 : B6 of B6

 TEL: 886-3-327-3456
 Issued Date
 : Oct. 22, 2010

 FAX: 886-3-318-0055
 FCC ID
 : RSE-TG703