7. Photographs

7.1. Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 Page No.
 : 80 of 97

 TEL: 886-2-2696-2468
 Issued Date
 : Oct. 22, 2009

 FAX: 886-2-2696-2255
 FCC ID
 : RSE-TG789VN



SIDE VIEW


 SPORTON International Inc.
 Page No.
 : 81 of 97

 TEL: 886-2-2696-2468
 Issued Date
 : Oct. 22, 2009


 FAX: 886-2-2696-2255
 FCC ID
 : RSE-TG789VN

7.2. Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW




REAR VIEW

 SPORTON International Inc.
 Page No.
 : 82 of 97


 TEL: 886-2-2696-2468
 Issued Date
 : Oct. 22, 2009

 FAX: 886-2-2696-2255
 FCC ID
 : RSE-TG789VN

For radiated emissions 30MHz~1GHz



FRONT VIEW




REAR VIEW

 SPORTON International Inc.
 Page No.
 : 83 of 97

 TEL: 886-2-2696-2468
 Issued Date
 : Oct. 22, 2009

 FAX: 886-2-2696-2255
 FCC ID
 : RSE-TG789VN

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 Page No.
 : 84 of 97

 TEL: 886-2-2696-2468
 Issued Date
 : Oct. 22, 2009

 FAX: 886-2-2696-2255
 FCC ID
 : RSE-TG789VN