Cellphone-Mate Inc. dba SureCall

\mathbf{r}	α	00	0 4
Dec	\mathbf{n}_{I}	'71	17/4
\mathbf{D}	UZ,	~\	<i>,∠</i> ⊤

Subject: Tuning and Adjustment of Signal booster, FCC ID: RSN-FIBERMAXMU

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Dennis Findley

DennisFindley