

Cellphone-Mate Inc. dba SureCall

Aug 10, 2023

Subject: Tuning and Adjustment of Signal booster, FCC ID: RSN-FUSION2GO5G

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Dennis Findley

A handwritten signature in black ink that reads "Dennis Findley". The signature is written in a cursive style with a large initial 'D' and 'F'.