

Cellphone-Mate Inc. dba SureCall

Dec 08, 2021

Subject: Tuning and Adjustment of Signal booster, FCC ID: RSN-FUSION5XMAX

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Dennis Findley

A handwritten signature in black ink that reads "Dennis Findley". The signature is written in a cursive style with a prominent loop at the end of the last name.