

FCC ID: RSNTRIFLEX-A
IC ID: ----
CT Project: TCB-p1370008

From: John Erhard
Date: 1/17/14

1. The users' manual on page 15 has a different FCC ID than the ID on the label. Please correct.

Cellphone-Mate – User's Manual has been updated

2. Per recent FCC communication it is required that the consumer notice on page 16 must match the example from KDB 935210 D02. The capitalized text must also be bold typeface. The E911 warning also does not match exactly. Please correct.

Cellphone-Mate - User's Manual has been updated

3. The block diagram has the quiescent current listed and this must be the current rating under full power. Please revise as necessary.

Cellphone-Mate – Please refer to Block Diagram Rev 2 exhibit

4. The schematics do not have any frequency range information for the various filter banks. Please either add information in the schematics or block diagram which correlate the two documents.

Cellphone-Mate – Please refer to Schematics Rev 2 exhibit

5. The Form 731 and the Label exhibit indicate the FCC ID is RSNTRIFLEX-A, but the test report lists the ID as RSNTRIFLEXA. Please correct as necessary.

CT – Form 731 has been updated

6. The MSCL exhibit has an indication for an MSCL limit. As there is not limit please remove this line item from the document or explain what it is and why it is necessary.

Cellphone-Mate – Please refer to MSCL Rev 3 exhibit.

Response by: Cellphone Mate and CTL

Submitted by: Compliance Testing LLC

Date: 1/31/14