

FCC ID: RU5AWBC1UP

Issued on Jul. 4, 2005

5.7.5. Photographs of Conducted Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 29 of 46 Issued Date : Jul. 4, 2005


Report No.: FR483129-30




FCC ID: RU5AWBC1UP

Issued on Jul. 4, 2005

5.8.8. Photographs of Radiated Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 41 of 46 Issued Date : Jul. 4, 2005

Report No.: FR483129-30