

## Mike Kuo

---

**From:** Claire Hoque  
**Sent:** June04日2004年Friday 11:16 AM  
**To:** Mike Kuo  
**Cc:** Tom Cokenias; Kathy Yao; Chuck Cowden  
**Subject:** RE: Skypilot Network Inc., FCC ID: RV7-SC1000, Assessment NO.: AN04T3944



User Manual  
(revised).pdf

Hi Mike,

Client added the statement on the last page, pls review the manual.  
Thanks,

Claire

-----Original Message-----

From: Mike Kuo  
Sent: Friday, June 04, 2004 9:01 AM  
To: Claire Hoque  
Cc: Tom Cokenias; Kathy Yao; Chuck Cowden  
Subject: RE: Skypilot Network Inc., FCC ID: RV7-SC1000, Assessment NO.: AN04T3944

Hi Claire :

Could not find the statement in the revised user manual to address question #2.

M.Kuo

-----Original Message-----

From: Claire Hoque  
Sent: Friday, June 04, 2004 9:48 AM  
To: Mike Kuo  
Cc: Tom Cokenias; Kathy Yao; Chuck Cowden  
Subject: RE: Skypilot Network Inc., FCC ID: RV7-SC1000, Assessment NO.: AN04T3944

Hi Mike,

Here are the answers.

Question #1: User manual does not contain information required per section 15.21 of FCC rules. Please provide revised user manual to address this requirement.

<answer>pls see revised user's manual.

Question #2: Restriction for co-located statement is missing. Please include a statement in the user manual to inform the installer that This device and its antenna(s) must not be co-located or operating in conjunction with any other antenna or transmitter. .

<answer>pls see revised user's manual.

Question #3: Please provide antenna specification sheet.

<answer>pls see the attached antenna spec.

Thanks,

Claire