




Skypilot Network Inc., FCC ID: RV7-SC3111, Assessment NO.: AN07T7217, Notice#1 [Inbox](#)

 **"tim.dwyer@ccsemc.com"** Hello Thu, September, The review of this application is complete. Please reply Sep 25 (2 days ago)

 from **September Radecki** <september.radecki@ccsemc.com> [hide details](#) 12:26 pm (30 minutes ago)  [Reply](#)

to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>
cc Thu Chan <thu.chan@ccsemc.com>
date Sep 27, 2007 12:26 PM
subject RE: Skypilot Network Inc., FCC ID: RV7-SC3111, Assessment NO.: AN07T7217, Notice#1

Hi Tim,

Below are the answers to your questions on this application.

Q1: Entries for Frequency Tolerance and Emission Designator were not included in the application form. This information is required for licensed devices. Please provide the information so that it can be entered in the application form.

<CCS Answer:> The frequency tolerance is 6.45 ppm. The emissions designators are 16M8W7D and 16M8G1D.

Q2: Please provide additional explanation for the Low Voltage Normal Temperature Results on page 38 of the test report. The explanation can be in the form of an email or test report addendum that will be included as an exhibit to the filing.

<CCS Answer:> Please see attached Revised Test Report.

Q3: Tune-up procedure and parts list exhibits are required for licensed transmitters. Please provide these exhibits.

<CCS Answer:> Parts List and Tune-up Procedure are attached.

Thanks and best regards,
September

September Radecki
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538
phone: 1-510-771-1090
fax: 1-510-661-0888
September.Radecki@CCSEMC.com <<mailto:September.Radecki@CCSEMC.com>>

[- Show quoted text -](#)

9 attachments — [Download all attachments](#)

-  **sc3130bom.pdf**
37K [View as HTML](#)
[Download](#)
-  **SC3111bom.pdf**
27K [View as HTML](#)
[Download](#)
-  **07U11263-1 FCC 90Y Report_Dual Band_setup photos.pdf**
301K [View as HTML](#) [Download](#)
-  **07U11263-1 FCC 90Y Report_Dual Band_no photos.pdf**
712K [View as HTML](#) [Download](#)
-  **Tuneup Procedure.pdf**
84K [View as HTML](#)
[Download](#)
-  **FCC Request for Confidentiality Revised.pdf**
87K [View as HTML](#) [Download](#)
-  **FCC Request for Confidentiality Revised 3130.pdf**
87K [View as HTML](#) [Download](#)
-  **07U11263-3 FCC 90Y Report_Single Band_no photos.pdf**
711K [View as HTML](#) [Download](#)



07U11263-3 FCC 90Y Report_Single Band_setup photos.pdf

302K [View as HTML](#) [Download](#)