



**To:**

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, Maryland 21046

**Subject:** FCC Class II Permissive Change request  
IC Reassessment

FCC ID: RVW2330B  
IC ID: 332R-2330B  
Model: 2330B

IEEE802.11 ABG access point radio

Gentlemen,

Nortel networks would like to request a Class II Permissive change / Reassessment for the above referenced product.

**Description of Change:** **Removal of 5 GHz bands that require DFS functionality.**

Currently the product is certified for operation in the 5.25 - 5.35 GHz UNII band. Due to the fact that the unit **DOES NOT** meet the FCC DFS requirements, Nortel is disabling this band via a firmware revision to the radio. There are no hardware changes being made to the unit and a field "upgrade" firmware that would enable this band again will **NOT** be made available.

If you have any questions, please do not hesitate to contact me at: [david@waitt.us](mailto:david@waitt.us) or (408) 832-7053

Sincerely,

A handwritten signature in black ink, appearing to read "David Waitt".

David Waitt  
Consultant representing Nortel