



Mike Kuo
<MKUO@CCSEMC.com>
2004/07/30 12:31 AM

收件人 : Lucy Tsai <lttsai@CCSEMC.com>
副本抄送 :
主旨 : FW: 回信 : FW: Action Star Enterprise Co., Ltd., FCCID:
RX4AT-111A, Assessment NO.: AN04T4053, Notice#3

-----Original Message-----

From: hliana@ccsemc.com.tw [mailto:hliana@ccsemc.com.tw]
Sent: Thursday, July 29, 2004 12:26 AM
To: Mike Kuo
Subject: 回信 : FW: Action Star Enterprise Co., Ltd., FCCID: RX4AT-111A, Assessment NO.: AN04T4053, Notice#3

Hi Mike,
Please find the answers to your questions as following blue text.

Thanks
Best regards,

熊連枝
Liana Hsiung

程智科技股份有限公司
Compliance Certification Services Inc.
(Hsintien Lab.)
No.165, Chunghsen Road, Hsintien City,
Taipei Hsien, Taiwan
TEL:+886-2-2217-0894*10
FAX:+886-2-2217-1029
Email: hliana@ccsemc.com.tw
URL: <http://www.ccsemc.com.tw>

Mike Kuo
<MKUO@CCSEMC.com> 收件人 : "'hliana@ccsemc.com.tw'" <hliana@ccsemc.com.tw>
副本抄送 :
主旨 : FW: Action Star Enterprise Co., Ltd., FCC ID:
RX4AT-111A, Assessment NO.: AN04T4053, Notice#3
2004/07/21 01:40 AM

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]

Sent: Tuesday, July 20, 2004 10:20 AM
To: mkuo@ccsemc.com
Subject: Action Star Enterprise Co., Ltd., FCC ID: RX4AT-111A, Assessment
NO.: AN04T4053, Notice#3

Question #1: Please explain the test condition during the radiated emission tests. The EUT was connected to Panasonic audio player, is audio player played any audio file with max. volume during the tests ?

-->Attached please find the page 6 (section 3.5) of the revised report have added explanation.

Question #2: Please provide peak emission data for fundamental frequency per

section 15.239(b) requirement .

-->Attached please find the page 15 of the revised report have added data.

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to

the e-mail address listed below the name of the sender.



C40403409-RP _Action Star AT-111A_Update.pdf