



August 2, 2004

attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

RE: Tune Up Procedure

To Whom It May Concern:

We, the undersigned, hereby state that the equipment known as the LPN Wireless "SafeTLink" with FCC type certification registration number RXV-STL-4TE1, has no field hardware adjustment points. All configuration changes possible are made via software, and are as described in the User Manual for this equipment. Therefore, we are not submitting a tune up procedure for the equipment.

Sincerely,

A handwritten signature in black ink that reads "Jerrold T. Hinshaw".

Jerrold T. Hinshaw
President,
LPN Wireless, Inc.