

Page : 391 of 395 Issued date : 2022/1/28

FCC ID : RYK-WNFQ268AXBT


Note:

For UNII-5, The Incumbent (AWGN) Signal Level is considered 0 dBi (-62dBm) gain for path loss, it will be more strict than EUT gain.

For UNII-6, The Incumbent (AWGN) Signal Level is considered 0 dBi (-62dBm) gain for path loss, it will be more strict than EUT gain.

For UNII-7, The Incumbent (AWGN) Signal Level is considered 0 dBi (-62dBm) gain for path loss, it will be more strict than EUT gain.

For UNII-8, The Incumbent (AWGN) Signal Level is considered 0 dBi (-62dBm) gain for path loss, it will be more strict than EUT gain.



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 392 of 395 Issued date : 2022/1/28

FCC ID : RYK-WNFQ268AXBT



Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 393 of 395 Issued date : 2022/1/28

FCC ID : RYK-WNFQ268AXBT



Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 394 of 395 Issued date : 2022/1/28

FCC ID : RYK-WNFQ268AXBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0988 / 1.0



Page : 395 of 395 Issued date : 2022/1/28

FCC ID : RYK-WNFQ268AXBT



END OF REPORT

Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0988 / 1.0