



10, 2175 - 29th Street NE Calgary AB Canada T1Y 7H8 / Ph 403 777 3760 Fax 403 777 3769  
www.mentoreng.com

Federal Communication Commission  
Equipment Authorization Division, Application Processing Branch  
7435 Oakland Mills Road  
Columbia, MD 21048

Mar 7, 2012

Dear FCC Examiner,

Mentor Engineering has made no modifications to the module that would impact RF performance in the following products:

<u>FCC ID Number</u>	<u>Product</u>	<u>Title/Model</u>
RZ3RAN45728		Ranger 4 EVDO

Tune up values are borrowed from the Sierra Wireless document "MC5728 Tune up and Alignment Procedure.pdf"

If you have any questions, please feel free to contact me at the address shown below.

Sincerely,

Dominic Pituch P.Eng  
Hardware Engineer  
10, 2175 - 29<sup>th</sup> St NE  
Calgary AB Canada  
T1Y 7H8