



Date: 06/11/2019

Re: § 2.933 Change in identification of equipment

To Whom It May Concern:

This change in identification of equipment request applies to the original FCC ID: JQ6-SE3200, granted on 2015-07-16. The equipment bearing the modified identification (new FCC ID: S38-SE3200) is electrically identical to the original equipment. Therefore, the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

Shiraz Kapadia, CEO & President

Phone No: 1-647-282-1745
Email: skapadia@invixium.com

Corporate Office

255 Consumers Road, Suite 110
Toronto, ON M2J 1R4
Canada

Tel: +1 844 INVIXIUM (468 4948)

experience@invixium.com

Branch Office

203-204 Elnaza Vertex
Sindhu Bhavan Road, Bodakdev, Ahmedabad
Gujarat 380059, India

INVIXIUM.COM