

Mobile Communications Inc.
230 Earl Stewart Drive
Aurora, Ont. Canada L4G 6V8
Tel: (905)726-3444 Fax:(905)726-4233

Jan. 29, 2014

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Subject: Tuning Procedure

Reference: S4RBRM22050
Model: BRM220-50

Dear Sir/Madam,

This device does not require any tune-up procedure, does not have any user configurable settings and the factory set NPS safeguards cannot be altered nor defeated by the user.

Sincerely,

A handwritten signature in black ink, appearing to read 'TV' or similar initials, written in a cursive style.

Tom Vagenas
Director ASO