

FCC ID: S7X5801A01 Issued on Sep. 15, 2005

Report No.: FR560207

5.5.5. Photographs of Conducted Emission Test Configuration



FRONT VIEW



REAR VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 22 of 43


Issued Date : Sep. 15, 2005




FCC ID: S7X5801A01 Issued on Sep. 15, 2005

Report No.: FR560207

5.6.11. Photographs of Radiated Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 35 of 43

Issued Date : Sep. 15, 2005



FCC ID: S7X5801A01 Issued on Sep. 15, 2005

Report No.: FR560207



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 36 of 43 Issued Date : Sep. 15, 2005