

## FCC ID: S9QP202S Issued on May 4, 2005

# 5.5.8. Photographs of Conducted Emission Test Configuration



FRONT VIEW



**REAR VIEW** 

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 23 of 44 Issued Date : May 4, 2005

Report No.: FR533142



# FCC ID: S9QP202S


Issued on May 4, 2005

## 5.6.11. Photographs of Radiated Emission Test Configuration

#### Mode 1



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 36 of 44 Issued Date : May 4, 2005

Report No.: FR533142



## FCC ID: S9QP202S Issued on May 4, 2005

Mode 2



FRONT VIEW



**REAR VIEW** 

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 37 of 44 Issued Date : May 4, 2005

Report No.: FR533142