

AC Power Line Carrier Current Requirement

February 11, 2010

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

RE: INSTEON 240V 30 AMP Load Controller (Dual-Band) #2477SA1 and #2477SA2

(FCC ID: SBP2477SA) IC: 5202A-2477SA

## Gentlemen:

This letter is to notify you that testing has not been completed for the AC power line, carrier current system portion of this equipment. The date of this testing has been set for <a href="May 1, 2010">May 1, 2010</a>. I hereby declare under penalty of perjury that the testing will be preformed on or before 1 year's time. If testing is not completed during this time frame then I understand that this application for certification could be revoked.

If you have any further questions or need additional information, please feel free to give me a call at  $949-221-0037 \times 147$ 

Sinderely.

Daniel B Cregg

VP and Chief Technology Officer

SmartLabs, Inc.

DBC/jtl



