



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 23, 2004

RE: OQO

FCC ID: SHD-A4YWFS

After a review of the submitted information, I have a few comments on the above referenced Application.

SAR Questions:

- 1) Although the calibration interval may be 18 months, the dipole calibration information is dated for July 2002 while testing was in November 2004. Please provide current calibration information for the dipole.
- 2) Please explain a DCP of 19. A DCP of 19 does not appear in the calibration information.
- 3) The last response states that the dielectric parameters are within 5%. Please show this in a table comparing the measured values to the expected values.
- 3) FYI.....Regardless of 15 cm, the FCC has asked that Z-axis scan information be provided with the SAR report. Checklists provided by the FCC have always included this. If available, please provide. If not, please be aware the FCC may still ask for this at a future time. Please be sure to include this in future applications.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.