

Non-Conformities FCC ID: SJC-M2140 (CKC CS Ref # E07-000124-FCC-01)

Non-Conformities FCC ID: SJC-M2140 (CKC CS Ref # E07-000124-FCC-01)

The items listed below represent requests for information following review of this application for certification under United States (FCC) regulations. Further question may arise pending review of responses to these items.

- 1 The RF exposure report appears to be incomplete. Please provide a final copy of this report with all items included.

Response: An updated MPE report has been uploaded.

- 2 Please explain the purpose of the M2510 duty cycle measurements provided in the operational descriptions.

Response: The M2150 duty cycle documentation covers the 2nd of two identical configurations of the same hardware. The only difference between the two devices from an RF perspective is the duty cycle percentage of the transmitter.

- 3 Please provide an updated users manual incorporating 15.21.

Response: An updated users manual has been uploaded.

- 4 The grantee code information does not match that listed on the provided form 731. If contact information has changed, it is the applicant's responsibility to contact the FCC to make the necessary changes. Please visit <https://fjallfoss.fcc.gov/eas/ModifyGrantee.do> -- No response necessary to this item.

Response: This has been corrected.

- 5 This application appears to be for modular approval, however there is no supporting letter requesting such treatment. The FCC has temporarily postponed the use of 15.212, please use reference to the DA00-1407 when writing the request.

Response: A letter requesting modular approval has been uploaded.

- 6 In accordance with DA00-1407, does the equipment have its own buffered input and outputs. Does the equipment have its own power supply regulation?

Response: This issue has been addressed in the letter requesting modular approval.