



In the XS3700 the rf boards only have two transceivers per board. The board shown is for the XS3900 which has all four transceivers installed. A separate photograph of the rf board with only two transceivers has been provided."