

DATE : April 19, 2017

Nemko North America Inc.  
Attn: Director of Certification  
303 River Road  
Ottawa, Ontario, Canada  
K1V 1H2

FCC ID: SKSH837A  
IC: 1052D-H837A  
HVIN: H837A  
PMN: BT-350

**Statement for original test reports**

The following test reports submitted in support of FCC ID: SKSH756A (Date of Grant: 12/01/2016), IC: 1052D-H756A, HVIN: H756A, PMN: BT-300, (Approval Date 2016-12-06) accurately represent the test results under the new conditions. Please refer to cover letter exhibit "FD12&IC12\_Model Differences Letter" for details.

1. 312742-1R1TRFWL (FCC 15.247 and RSS-247 802.11bgn), November 28, 2016
2. 312742-2TRFWL(FCC 15.407 and RSS-247 5.2 GHz), November 24, 2016
3. 312742-3TRFWL(FCC 15.407 and RSS-247 5.3 GHz), November 30, 2016
4. 312742-4TRFWL(FCC 15.407 and RSS-247 5.6 GHz), November 30, 2016
5. 312742-5R1TRFWL(FCC 15.407 and RSS-247 5.8 GHz), November 28, 2016
6. 312742-6TRFWL(15.247 and RSS-247 FHSS BT), November 24, 2016
7. 312742-7TRFWL(FCC-15.247 and RSS-247 2.4 GHz BLE), November 24, 2016
8. H756A FCC Rev A, Test Report Number: SAR.20161103, Revision A

**Dated this** 19 **Day of** April **20** 17

**By:** 津田 敦 **Signature** Atsunari Tsuda **Printed**

**Title:** General Manager

**On behalf of :** Seiko Epson Corporation

**Telephone:** +81-263-87-5881