

## INTERTEK TESTING SERVICE


---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

## Equipment Photographs

Model: AN9BG3

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

## Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: HK13020275-2

### Equipment Photographs

Model: AN9BG3

(Internal)

