

scott

To: kyle@celectronics.com; mike@celectronics.com

Subject: FCC ID: SOXW9400

Mr. Fujimoto:

In order for processing of this application (FCC ID: SOXW9400) to continue, the following issue(s) will have to be addressed:

1) The internal photos submitted do not show the bottom side of the circuit board clearly. Please submit new photo(s).

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is SOXW9400-1.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-0500
Direct: (714) 579-1489
Fax: (714) 579-1850
scott@celectronics.com

Correspondence by Project

Project Number:

1100918347

Correspondence Number	Memo
SOXW9400-1	<p>1. The bottom side of the PCB was not included in the main file for the Internal Pictures. The file has been revised to include the bottom side of the PCB. Please see the Revised Internal Pictures Exhibit.</p>