

Rhein Tech Laboratories, Inc.  
360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

Client: IWT  
Model #: FAP6210-001  
Standards: FCC 15.247 & IC RSS-210  
ID's: SP8-FAP6210001/9568A-FAP6210001  
Report #: 2012174

## **Appendix A: Change Description**

Please refer to the following page.



Innovative Wireless Technologies  
1047 Vista Park Dr. Suite A  
Forest, VA 24551  
Phone: 434.316.5230  
Fax: 434.316.5232

June 6, 2012

American Certification Body, Inc.  
6731 Whittier Avenue  
Suite C110  
McLean, VA 22101

To Whom It May Concern:

The following changes have been made since the original certification of the IWT Sentinel Handset.

To the SBB020004 PCB:

- The manufacturer for fuse F2 has been changed.
- Resistors R1, R2, R4, R6 - R9, R14, R21, R22, R24, R27 - R31, R41 - R44, R82 - R86, R88, R108, and R117 have been changed to 1.2kohms.
- Conformal coating has been added.

To the SBB010008 PCB:

- The manufacturer for fuses F1 and F2 have been changed.
- Resistors R38, R40, R46, R51 - R55, R61, R63, R98, and R100 have been changed to 1.2kohms.
- U5 has been changed to a different part.
- The value of the capacitors C21 – C25 have changed.
- The value of the inductors L3 – L5 in the output filter have changed.
- Conformal coating has been added.

Thank you for your attention to this matter.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Gary J. Raulerson'.

Gary Raulerson  
New Products Introduction Manager  
Innovative Wireless Technologies, Inc.