


Test Date: 02-14-07
Company: Reliance Controls
EUT: 11034
Test: 5 second TX stop requirement
Operator: Tim Lusha

Transmission stops after 332.67 ms.



Date: 14.FEB.2007 13:46:12