



INTERTEK TESTING SERVICES

Report No.: HK12050275-1
Sample No.: 1/1



Bandedge Pot – Pursuant to FCC Part 15 Section 15. 249 Requirement

(Pass/Fail)