

---

# INTERTEK TESTING SERVICE



---

Report No.: HK10060819-1

## Equipment Photographs

Model : QXG7583

(Internal)



---

FCC ID: SQ9QXG7583  
IC: 5768A-QXG7583



# INTERTEK TESTING SERVICE

Report No.: HK10060819-1

## Equipment Photographs

Model : QXG7583

(Internal)



FCC ID: SQ9QXG7583  
IC: 5768A-QXG7583



# INTERTEK TESTING SERVICE

Report No.: HK10060819-1

## Equipment Photographs

Model : QXG7583

(Internal)



FCC ID: SQ9QXG7583  
IC: 5768A-QXG7583




# INTERTEK TESTING SERVICE

Report No.: HK10060819-1

## Equipment Photographs

Model : QXG7583

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report No.: HK10060819-1

## Equipment Photographs

Model : QXG7583

(Internal)



---

FCC ID: SQ9QXG7583  
IC: 5768A-QXG7583