



INTERTEK TESTING SERVICES

Report No.: HK12050279-1
Sample No.: 1/1



Bandedge Pot – Pursuant to FCC Part 15 Section 15.249 Requirement

(Pass/Fail)