


US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Nivis Module Board, with Shield

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Nivis Module Board, without Shield

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Back View of Nivis Module Board

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Front View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Back View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Back View of Internal Boards

US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:


FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Back View of Internal Boards


US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Airnode




US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode




US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode




US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode




US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode




US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



US TECH
Test Report:
Report Number: 07-0245
Customer:
Model:

FCC ID: SQB-NIVISAN0010
FCC Spread Spectrum Radio
Issue Date: 27 December 2007
Nivis, LLC
2.4 GHz Ainode



Radio Close up

