



RTR-50  
(FCC ID: SRDRTR50)  
explaining the changes

Sharon Hoffman  
Timco Engineering

Dear Ms. Hoffman;

Owing to discontinuation by our previous supplier, TandD finds that it must change manufacturers of the SAW filter that we use in our RTR-50 wireless data bases. The components affected by this change are shown in the table below. We would like to request that Timco Engineering perform retesting on these products to confirm that the modified products still conform to the relevant FCC Part 15 Rules, and if so to submit the necessary filings for a Class II Permissive Change.

Parts Changes

Reference	Before Modification		After Modification	
	Part No	Manufacture	Part No	Manufacture
F1	WFSTSM915AW-6	SANYO	WF998D0915CE	NDK
C42	GRM1882C1H5R0CZ01 D	Murata	GRM1882C1H4R0CZ01 D	Murata
C220	GRM1882C1H9R0DZ01 D	Murata	LQW18AN6N8C00D	Murata
C221	GRM1882C1H9R0DZ01 D	Murata	GRM1882C1H200JA01D	Murata
L205	LQW18AN18NG00D	Murata	LQW18AN47NG00D	Murata

Sincerely,

Akemi Oana  
TandD Corporation