Report No.: LCS1512161383E

1. INTERIOR PHOTOGRAPHS





Fig.1



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 1 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: SS4SF550 Report No.: LCS1512161383E




Fig.3



Fig.4

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 2 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID: SS4SF550

Report No.: LCS1512161383E




Fig.5




Fig.6

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 3 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: SS4SF550 Report No.: LCS1512161383E




Fig.7




Fig.8

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 4 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID: SS4SF550

Report No.: LCS1512161383E



Fig.9




Fig.10

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 5 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FO

FCC ID: SS4SF550

Report No.: LCS1512161383E




Fig.11

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 6 of 6