



Federal Communications Commission
Authorization & Evaluation Division
7345 Oakland Mills Rd
Columbia, Maryland 21046

Date: January 16, 2012

Re: Revised FCC Part 90/Part22 Test Report
ISC Technologies Inc
FCC ID: SS6ISC-T5340

To Whom It May Concern,
Compliance Testing has made us aware of the error that was made in the FCC
Part 90/Part 22 Test Report Rev 1.0.

The original FCC Part 90 / Part 22 Rev 1.0 Test Report had incorrect tuned
frequencies listed in the Conducted Spurious Emissions Summary Test Table on
page 10. This table has been revised to list the correct tuned frequencies.

We have received the FCC Part 90 / Part 22 Rev 2.0 Test Report and have
reviewed its contents verifying that there were no other changes made.

Respectfully,



Tim Anderson
Vice President
ISC Technologies, Inc

ISC Technologies, Inc.
910 Broadway, Suite B
Quincy, IL 62301

217-221-0985
Fax: 217-221-9775
www.isc@4isctech.com
www.4isctech.com