




132604_1_f.JPG: EPI7674 inside H6780BP, internal view 1 (cover removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 1 of 7






132604_1_k.JPG: EPI7674 inside H6780BP, internal view to main PCB

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 2 of 7






132604_1_m.JPG: EPI7674 inside H6780BP, internal view to rf PCB on main PCB

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 3 of 7





132604_1_q.JPG: EPI7674 bottom view

Test Report No.: F132604E1, 2nd version Order No.: 13-112604 Examiner: Thomas KÜHN Date of issue: 23 May 2014

page 4 of 7






132604_1_s.JPG: EPI7674 bottom view, type plate removed

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 5 of 7





132604_1_r.JPG: EPI7674 top view


 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 6 of 7



page 7 of 7

ANNEX C: INTERNAL PHOTOGRAPHS



132604_1_p.JPG: EPI7674 inside H6780BP, antenna view

Examiner: Thomas KÜHN Date of issue: 23 May 2014

Test Report No.: F132604E1, 2nd version Order No.: 13-112604