


132604_3_e.JPG: EPI7674 inside H6780BP2, internal view 1 (cover removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 1 of 7





132604_3_f.JPG: EPI7674 inside H6780BP2, internal view to main PCB

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 2 of 7





132604_3_g.JPG: EPI7674 inside H6780BP2, internal view to rf PCB on main PCB

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 3 of 7






132604_3_j.JPG: EPI7674 bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 4 of 7






132604_3_k.JPG: EPI7674 bottom view, type plate removed

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 5 of 7





132604_3_i.JPG: EPI7674 top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604
 page 6 of 7



page 7 of 7

ANNEX C: INTERNAL PHOTOGRAPHS



132604_3_d.JPG: EPI7674 inside H6780BP2, antenna view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E3, 2nd version

 Date of issue:
 23 May 2014
 Order No.:
 13-112604