



132604_1_1.JPG: EPI7674 inside H6780BP, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1

 Date of issue:
 25 October 2013
 Order No.:
 13-112604
 page 1 of 4





132604_1_2.JPG: EPI7674 inside H6780BP, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1

 Date of issue:
 25 October 2013
 Order No.:
 13-112604
 page 2 of 4





132604_1_3.JPG: EPI7674 inside H6780BP, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1

 Date of issue:
 25 October 2013
 Order No.:
 13-112604
 page 3 of 4





132604_1_8.JPG: EPI7674 inside H6780BP, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132604E1

 Date of issue:
 25 October 2013
 Order No.:
 13-112604
 page 4 of 4